



BORAHURST LTD

75 BELL STREET · REIGATE · SURREY · RH2 7AN

T: 01737 221733 · F: 01737 223512

E: INFO@BORAHURST.COM · WWW.BORAHURST.COM

ESTABLISHED 1977

SERVICE ENGINEERS REPORT

CUSTOMER:
ASHTEAD SQUASH AND TENNIS CLUB
ENGINEER: CRAIG WALKER

SITE:
39 SKINNERS LANE ASHTEAD
DATE: 26/6/17

PARTS FITTED	REPLACEMENT PARTS FITTED
SITE TIME: 11.30 – 2.30	TRAVELLING TIME: 60 MINUTES
MILEAGE: 20	CONGESTION CHARGE Y/N: NO

CARRIED OUT FULL STRIP DOWN AND DEEP CLEAN OF 1X MITUBISHI ELECTRIC SPLIT SYSTEM LOCATED IN THE STUDIO.
 STRIPPED UNIT DOWN BACK TO COILL
 REMOVED FACIA AND CLEANED
 REMOVED ELECTRICS BOX TO GAIN ACCESS TO DRIP TRAY
 REMOVED DRIP TRAY AND CLEANED REMOVED ALL SLIME AND DIRT
 CLEANED INTERNAL PUMP REMOVING ALL SLIME
 ROMOVED FAN BLADE AND CLEANED
 CLEANED COIL USING RTU DISINFECTANT AND BRUSH
 CLEANED FILTER
 PUT UNIT BACK TOGETHER
 CHECKED ELECTRICS AND ISOLATORS
 CARRIED OUT COMPONANT TESTS eg compressor amps
 CARRIED OUT PERFORMANCE TESTS – ALL OK

ENGINEERS SIGNATURE: Craig Walker
